

To : PISCO Distributors  
Attn. : To Whom It May Concerns  
Date : August 2022

Dear PISCO Distributors,

**Re: Discontinuation of Rotary actuator (HR200/400 series)**

We would like to express our sincere gratitude for your continued patronage.

We would like to take this opportunity to inform you about the "Rotary Actuator HR200/400 Series" that has been patronized by you for a long time, but we have decided to end the production.

We apologize for the inconvenience, but we appreciate your understanding and cooperation. Thank you very much for your patronage. We look forward to your continued patronage in the future.

1. End of production: End of March 2023

\*Depending on the order status, the production end date may be brought forward, but we ask for your understanding.

2. Main reasons for discontinuing production

- 1) It is difficult to continuously maintain and manage the aluminum extrusion die for the cylinder, which is a major component.
- 2) Because it became impossible to manufacture parts due to aging of the cushion pad (rubber) mold, which is a mechanical part.

We decided to discontinue production for the above reasons and because we can assume that the sales volume is not enough to continue production.

3. Discontinued products

- ①HR200-90(D) Pinion shaft type/Rotating disk type
- ②HR400-90(D) Pinion shaft type/Rotating disc type
- ③HR400-180(D) Pinion shaft type/Rotating disk type

\*Includes options

4. Service parts

Maintenance parts storage period End of March 2024

5. Successor/alternative products

There is no successor or substitute for the HR200/400 series.

Please make inquiries to following sales office.

**Overseas Sales Department TEL : +81-(0)265-76-7751**

**FAX : +81-(0)265-76-3305**

**E-mail : [intl@pisco.co.jp](mailto:intl@pisco.co.jp)**

**URL : <http://en.pisco.co.jp/>**